TYVION

Mass Spectrometer Tuning Issues and Troubleshooting **Methods**



Fault Symptom:

When tuning parameters are adjusted, the change in tuning peak intensity is delayed.

Possible Causes and Solutions:

The ion source is contaminated.

Solution: Clean the ion source with methanol and acetone using ultrasonic cleaning for 15 minutes each.

The pre-quadrupole is contaminated.

Solution: Clean the pre-quadrupole rod with methanol and acetone using ultrasonic cleaning for 15 minutes each.

The ion source components are not properly installed, causing a poor circuit connection.

Solution: Remove the ion source and reinstall it correctly.

Fault Symptom:

Excessive ion energy and repulsion voltage are required when tuning the mass spectrometer.

Possible Causes and Solutions:

High ion energy is due to a polluted ion source, and high repulsion voltage is due to contamination of the pre-quadrupole and quadrupole rods.

Solution: Clean the ion source, pre-quadrupole rod, and quadrupole rod with methanol and acetone using ultrasonic cleaning for 15 minutes each, and perform routine maintenance.



🛟 The mass spectrometer is not optimally tuned. **Solution:** Retune the mass spectrometer.

Fault Symptom:

The instrument response is not noticeable when tuning parameters are changed.

Possible Causes and Solutions:

The ion source may be short-circuited, or the circuit may be disconnected. Solution: Remove the ion source and use a multimeter to check whether the circuit connections between components are functioning correctly.

Fault Symptom:

The tuning peak shape is poor, with a shoulder peak present.

Possible Causes and Solutions:

- The mass spectrometer is not optimally tuned. **Solution:** Retune the mass spectrometer.
- The ion source is contaminated.

Solution: Clean the ion source with methanol and acetone using ultrasonic cleaning for 15 minutes each.

The analyzer is defective or damaged. **Solution:** Inspect the analyzer for defects or damage.

Fault Symptom:

No reference peak appears during tuning.

Possible Causes and Solutions:

The reference standard (perfluorobutylamine) bottle is empty. Solution: Add the reference standard to the sample bottle built into the mass spectrometer.

. . .

 \downarrow

The reference standard pipeline is blocked.

Solution: Remove the pipeline and clean it with acetone using ultrasonic cleaning.

🕻 Air leakage.

Solution: Check the height of the air peak at m/z 28. If it is greater than 10% of the helium peak at m/z 4, it indicates an air leak. Use a syringe to drop acetone at each interface, and observe the intensity change of the acetone molecular ion peak at m/z 58 to pinpoint the exact location of the leak.

Fault Symptom:

Tuning peaks are irregular and rough.

Possible Causes and Solutions:

The ion source is contaminated.

Solution: Clean the ion source with methanol and acetone using ultrasonic cleaning for 15 minutes each.

Filament aging.

Solution: Replace the filament.

The mass spectrometer is not optimally tuned.
Solution: Retune the mass spectrometer.

Fault Symptom:

Peaks at m/z 18, 28, and 32 are greater than 10% of the helium peak at m/z 4.

Possible Causes and Solutions:

🚺 Air leakage.

Solution: Perform leak detection and check the connection of the column.

The helium supply is nearly exhausted, leading to impurity buildup in the gas cylinder.

Solution: Replace the carrier gas cylinder and install a degassing device.

The newly cleaned ion source has not been dried. **Solution:** Bake the ion source at 250°C.

The column is contaminated.Solution: Age the column.

Fault Symptom:

No ions are generated even though the filament is in good condition.

Possible Causes and Solutions:

The ion source needs recalibration.
Solution: Recalibrate the ion source using a calibration tool.

Severe air leakage.
Solution: Detect the leak and tighten the connections.

Fault Symptom:

High-mass peaks at m/z 502 and 614 do not appear during tuning.

Possible Causes and Solutions:

The pre-quadrupole rod is short-circuited. **Solution:** Remove the pre-quadrupole rod and dry it with helium or nitrogen.

www.tyvion.com

service@tyvion.com

+1 (888) 840 1793

6615 Vaught Ranch Rd., Suite G10, Austin, TX 78730

Our main office located in Austin, TX, but we cover all of the U.S.